

AQUA LUNG Military Tech Bulletin

Military & Professional

**SUBJECT: UPDATE TO G2000SS & G3000SS SERVICE KITS
Bulletin No 18-002**

Products Affected:



- Aqua Lung G2000SS Annual Service Kit PN 400108
- Aqua Lung G3000SS Annual Service Kit PN 400180 & PN 400183

Issue:

This bulletin serves to notify customers of a change to the G2000SS and G3000SS annual service kits. Each service kit previously contained two manifold plug o-rings PN 400031, one for the manifold plug PN 400030 and one for the bulkhead comms plug PN 400017. Updated service kits will now contain one manifold plug o-ring PN 400201P and one comms penetrator o-ring PN 400031.

Corrective Action:

All service kit cards and technical manuals have been updated to reflect the necessary mentioned changes as of May 30, 2018.



For further technical support on any of the information presented please contact:

Steve Reilly - Aqua Lung Military Product Manager: sreilly@aqualung.com